


Macroseismic Intensity Map  
 USGS ShakeMap: 15 km E of Kirkağaç, Manisa, TR  
 Jan 22, 2020 19:22:16 UTC M5.6 N39.08 E27.85 Depth: 8.6km ID:us60007d2r



SHAKING	Not felt	Weak	Light	Moderate	Strong	Very strong	Severe	Violent	Extreme
DAMAGE	None	None	None	Very light	Light	Moderate	Moderate/heavy	Heavy	Very heavy
PGA(%g)	<0.05	0.3	2.76	6.2	11.5	21.5	40.1	74.7	>139
PGV(cm/s)	<0.02	0.13	1.41	4.65	9.64	20	41.4	85.8	>178
INTENSITY	<b>I</b>	<b>II-III</b>	<b>IV</b>	<b>V</b>	<b>VI</b>	<b>VII</b>	<b>VIII</b>	<b>IX</b>	<b>X+</b>

Scale based on Worden et al. (2012)

Version 3: Processed 2020-01-22T21:22:55Z

△ Seismic Instrument ○ Reported Intensity

★ Epicenter